

WA 2917 42
9/22/1987

WEEKLY TANK INSPECTION REPORT

The following tanks were inspected for corrosion, leaking valves, seams or manholes.

CL #	OK	NEEDS REPAIR	TANK #	OK	NEEDS REPAIR
90			105	✓	
91			106	✓	
92			107	✓	
93			108	✓	
94			109	✓	
95			110	✓	Broken cover plate
96			111	✓	
97			112	✓	
98			113		PNO
99			114	✓	
100			115	✓	
101			116	✓	
102			117	✓	
103			118	✓	
104			165	✓	



FILE COPY

All tank yard berms OK NEEDS REPAIR _____
SEAL YARD berms OK NEEDS REPAIR _____
yard berms OK NEEDS REPAIR _____
ADDITIONAL COMMENTS _____

Reported for the week of 9-22-87 1987
Signed Matthew Williams



WEEKLY TANK INSPECTION REPORT

The following tanks were inspected for corrosion, leaking valves, seams or manholes.

TANK #	OK	NEEDS REPAIR	TANK #	OK	NEEDS REPAIR
90	<input checked="" type="checkbox"/>	_____	105	<input checked="" type="checkbox"/>	_____
91	<input type="checkbox"/>	_____	106	<input checked="" type="checkbox"/>	_____
92	<input type="checkbox"/>	_____	107	<input checked="" type="checkbox"/>	Coils leak
93	<input type="checkbox"/>	_____	108	<input checked="" type="checkbox"/>	_____
94	<input checked="" type="checkbox"/>	_____	109	<input checked="" type="checkbox"/>	_____
95	<input type="checkbox"/>	_____	110	<input checked="" type="checkbox"/>	Boom Cable
96	<input checked="" type="checkbox"/>	_____	111	<input checked="" type="checkbox"/>	_____
97	<input checked="" type="checkbox"/>	_____	112	<input checked="" type="checkbox"/>	_____
98	<input checked="" type="checkbox"/>	_____	113	<input type="checkbox"/>	PNO
99	<input checked="" type="checkbox"/>	_____	114	<input checked="" type="checkbox"/>	_____
100	<input checked="" type="checkbox"/>	_____	115	<input checked="" type="checkbox"/>	_____
101	<input type="checkbox"/>	_____	116	<input checked="" type="checkbox"/>	_____
102	<input type="checkbox"/>	_____	117	<input checked="" type="checkbox"/>	_____
103	<input type="checkbox"/>	_____	118	<input checked="" type="checkbox"/>	_____
104	<input type="checkbox"/>	_____	165	<input checked="" type="checkbox"/>	_____

All tank yard berms OK NEEDS REPAIR _____

SEAL YARD berms OK NEEDS REPAIR _____

1 yard berms OK NEEDS REPAIR _____

ADDITIONAL COMMENTS _____

Reported for the week of 4-23-87 19__

Signed [Signature]

WEEKLY TANK INSPECTION REPORT

The following tanks were inspected for corrosion, leaking valves, seams or manholes.

NO. #	OK	NEEDS REPAIR	TANK #	OK	NEEDS REPAIR
30	<input checked="" type="checkbox"/>		105	<input checked="" type="checkbox"/>	
31			106	<input checked="" type="checkbox"/>	
32			107	<input checked="" type="checkbox"/>	
33	<input checked="" type="checkbox"/>		108	<input checked="" type="checkbox"/>	
34			109	<input checked="" type="checkbox"/>	
35			110	<input checked="" type="checkbox"/>	Call room broken
36	<input checked="" type="checkbox"/>		111	<input checked="" type="checkbox"/>	
37	<input checked="" type="checkbox"/>		112	<input checked="" type="checkbox"/>	
38	<input checked="" type="checkbox"/>		113		PNCO
39	<input checked="" type="checkbox"/>		114	<input checked="" type="checkbox"/>	
40	<input checked="" type="checkbox"/>		115	<input checked="" type="checkbox"/>	
41			116	<input checked="" type="checkbox"/>	
42			117	<input checked="" type="checkbox"/>	
43			118	<input checked="" type="checkbox"/>	
44			165	<input checked="" type="checkbox"/>	

11 tank yard berms OK NEEDS REPAIR

SEL YARD berms OK NEEDS REPAIR

yard berms OK NEEDS REPAIR

ADDITIONAL COMMENTS

Reported for the week of 9-24-87 1987

Signed Walt Mathews

WEEKLY TANK INSPECTION REPORT

The following tanks were inspected for corrosion, leaking valves, seams or manholes.

NO. #	OK	NEEDS REPAIR	TANK #	OK	NEEDS REPAIR
90	<input checked="" type="checkbox"/>		105	<input checked="" type="checkbox"/>	
91		<u>PNO</u>	106	<input checked="" type="checkbox"/>	
92		<u>PNO</u>	107	<input checked="" type="checkbox"/>	
93		<u>PNO</u>	108	<input checked="" type="checkbox"/>	
94	<input checked="" type="checkbox"/>		109	<input checked="" type="checkbox"/>	
95		<u>PNO</u>	110	<input checked="" type="checkbox"/>	<u>Boom Cable Broken</u>
96	<input checked="" type="checkbox"/>		111	<input checked="" type="checkbox"/>	
97	<input checked="" type="checkbox"/>		112	<input checked="" type="checkbox"/>	
98	<input checked="" type="checkbox"/>		113		<u>PNO</u>
99	<input checked="" type="checkbox"/>		114	<input checked="" type="checkbox"/>	
100	<input checked="" type="checkbox"/>		115	<input checked="" type="checkbox"/>	
101			116	<input checked="" type="checkbox"/>	
102			117	<input checked="" type="checkbox"/>	
103		<u>PNO</u>	118	<input checked="" type="checkbox"/>	
104			165	<input checked="" type="checkbox"/>	

All tank yard berms OK NEEDS REPAIR

SEEL YARD berms OK NEEDS REPAIR

yard berms OK NEEDS REPAIR

ADDITIONAL COMMENTS

Exam rim ok. No damage to structure wall.

Reported for the week of 9-25 1987

Signed Walt Mathews